



2.0 Safety Features

STANDARD FEATURES

All of W. E. Plemons Machine Services, Inc. machines come with the following standard safety features:

1. Strobe light to indicate when there is power to machine.
2. Safety guards on front and rear.
3. Side panel guards on drive train.
4. Safety interlocks on all guards; front, rear, and side panels.

SAFETY PROCEDURES

As with all machinery, injury can result if safety procedures are not adhered to. The following are some of the safety rules that should be incorporated into your plant safety program and put into practice by all of your maintenance and operating personnel:

1. Always lock out machine before doing maintenance or adjustments on equipment.
2. Never run the machine without the guards in place.
3. This machine is equipped with hot melt glue applicators always wear protective equipment when working around hot melt units.
4. Always check machine for worn or loose parts and replace and tighten as needed before starting.
5. This machine operates on high voltage and only qualified electricians should work on electrical components.
6. Always be aware that this machine can start automatically when in the auto position and downstream control contact and/or time delay attachment is used.
7. Always wear proper clothing and protective equipment.
8. This machine should be operated by trained and qualified personnel only.

Tray Box Former



THIS PAGE IS BLANK